


# Operations Report

Driver Number	17614681	Report Page	1 of 1
Driver Name	17614681	Date Range	10/01/2020 12:34 - 12:47
Vehicle Number	22325	Total Engine Hours	00:12:44
Total Kms	4	Hours Of Idling	00:02:38 (21%)
Ending Odometer	731321	Hours Over 1800 RPM	00:00:00
Brakes Time	00:01:47	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	28/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

## Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	00:06:10	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:06:10
800-900	00:00:30	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:30
900-1000	00:01:19	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:19
1000-1100	00:01:40	00:00:15	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:55
1100-1300	00:01:41	00:00:09	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:50
1300-1400	00:00:29	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:29
1400-1500	00:00:13	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:13
1500-1600	00:00:08	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:08
1600-1700	00:00:03	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:03
1700-1800	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
1800-2000	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	00:12:13	00:00:24	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:12:37

## Time Analysis



## General Operation

Total Fuel	3 litres	Fuel per 100kms	75 litres	Kms Per Litre	1.333
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


# Activity Report

Driver Number	17614681	Report Page	1 of 1
Driver Name	17614681	Date Range	10/01/2020 12:34 - 12:47
Vehicle Number	22325	Total Engine Hours	00:12:44
Total Kms	4	Hours Of Idling	00:02:38 (21%)
Ending Odometer	731321	Hours Over 1800 RPM	00:00:00
Brakes Time	00:01:47	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	28/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
10/01/2020	12:34:49	12:47:33	Key Off	00:12:44	4	00:10:06	00:02:38	3	00:00:00	
				00:12:44	4	00:10:06	00:02:38	3	00:00:00	00:00:00

# Activity Graph

Driver Number	17614681	Report Page	1 of 1
Driver Name	17614681	Date Range	10/01/2020 12:34 - 12:47
Vehicle Number	22325	Total Engine Hours	00:12:44
Total Kms	4	Hours Of Idling	00:02:38 (21%)
Ending Odometer	731321	Hours Over 1800 RPM	00:00:00
Brakes Time	00:01:47	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	28/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



# Administration Report

Driver Number	17614681	Report Page	1 of 1
Driver Name	17614681	Date Range	10/01/2020 12:34 - 12:47
Vehicle Number	22325	Total Engine Hours	00:12:44
Total Kms	4	Hours Of Idling	00:02:38 (21%)
Ending Odometer	731321	Hours Over 1800 RPM	00:00:00
Brakes Time	00:01:47	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	28/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
10/01/2020 12:34:49	Key On at Customer_Minto with an odometer of 731317 and fuel count 281028.9
10/01/2020 12:37:27	Idle Event at Customer_Minto for 158 seconds.
10/01/2020 12:40:37	Location Customer_Minto -> Minto
10/01/2020 12:43:37	Location Minto -> Campbelltown
10/01/2020 12:47:33	Key Off at Campbelltown with an odometer of 731321 and fuel count 281031.2
10/01/2020 12:47:38	Completed Trip with Odometer 731321 and Fuel 281031.2