

# Operations Report

Driver Number	401503629	Report Page	1 of 1
Driver Name	Jason Taylor	Date Range	12/02/2020 18:56 - 19:42
Vehicle Number	22344	Total Engine Hours	00:46:39
Total Kms	2	Hours Of Idling	00:42:30 (91%)
Ending Odometer	770899	Hours Over 1800 RPM	00:00:11
Brakes Time	00:01:39	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	6/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

## Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-101	101-103	103-105	105+	Aux	Total
0-800	00:43:49	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:43:49
800-900	00:00:15	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:15
900-1000	00:00:22	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:22
1000-1100	00:00:37	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:37
1100-1300	00:00:51	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:51
1300-1400	00:00:19	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:19
1400-1500	00:00:08	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:08
1500-1600	00:00:04	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:04
1600-1700	00:00:02	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:02
1700-1800	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
1800-2000	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:01
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:04	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:04
Total	00:46:32	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:46:32

## Time Analysis



## General Operation

Total Fuel	6 litres	Fuel per 100kms	300 litres	Kms Per Litre	0.333
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms

# Activity Report


Driver Number	401503629	Report Page	1 of 1
Driver Name	Jason Taylor	Date Range	12/02/2020 18:56 - 19:42
Vehicle Number	22344	Total Engine Hours	00:46:39
Total Kms	2	Hours Of Idling	00:42:30 (91%)
Ending Odometer	770899	Hours Over 1800 RPM	00:00:11
Brakes Time	00:01:39	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	6/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
12/02/2020	18:56:13	19:42:52	Key Off	00:46:39	2	00:04:09	00:42:30	6	00:00:00	
				00:46:39	2	00:04:09	00:42:30	6	00:00:00	00:00:00

# Activity Graph

Driver Number	401503629	Report Page	1 of 1
Driver Name	Jason Taylor	Date Range	12/02/2020 18:56 - 19:42
Vehicle Number	22344	Total Engine Hours	00:46:39
Total Kms	2	Hours Of Idling	00:42:30 (91%)
Ending Odometer	770899	Hours Over 1800 RPM	00:00:11
Brakes Time	00:01:39	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	6/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



# Administration Report

Driver Number	401503629	Report Page	1 of 1
Driver Name	Jason Taylor	Date Range	12/02/2020 18:56 - 19:42
Vehicle Number	22344	Total Engine Hours	00:46:39
Total Kms	2	Hours Of Idling	00:42:30 (91%)
Ending Odometer	770899	Hours Over 1800 RPM	00:00:11
Brakes Time	00:01:39	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	6/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
12/02/2020 18:56:13	Key On at Minto with an odometer of 770897 and fuel count 292646.7
12/02/2020 19:02:43	Idle Event at Minto for 390 seconds.
12/02/2020 19:06:19	Location Minto -> Customer_Minto
12/02/2020 19:42:42	Idle Event at Customer_Minto for 2160 seconds.
12/02/2020 19:42:52	Key Off at Customer_Minto with an odometer of 770899 and fuel count 292652.4
12/02/2020 19:42:57	Completed Trip with Odometer 770899 and Fuel 292652.4