

# Operations Report

Driver Number	408094944	Report Page	1 of 1
Driver Name	408094944	Date Range	29/07/2020 14:10 - 14:36
Vehicle Number	22325	Total Engine Hours	00:25:16
Total Kms	13	Hours Of Idling	00:02:07 (8%)
Ending Odometer	802769	Hours Over 1800 RPM	00:00:04
Brakes Time	00:03:44	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	29/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

## Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	00:09:34	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:09:34
800-900	00:00:47	00:00:05	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:52
900-1000	00:02:42	00:00:24	00:00:03	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:03:09
1000-1100	00:02:56	00:00:35	00:00:52	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:04:23
1100-1300	00:03:29	00:00:26	00:00:22	00:00:47	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:05:04
1300-1400	00:00:53	00:00:05	00:00:06	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:04
1400-1500	00:00:26	00:00:00	00:00:00	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:27
1500-1600	00:00:16	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:16
1600-1700	00:00:08	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:08
1700-1800	00:00:03	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:03
1800-2000	00:00:03	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:03
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	00:21:17	00:01:35	00:01:23	00:00:48	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:25:03

## Time Analysis



## General Operation

Total Fuel	6 litres	Fuel per 100kms	46 litres	Kms Per Litre	2.167
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


# Activity Report

Driver Number	408094944	Report Page	1 of 1
Driver Name	408094944	Date Range	29/07/2020 14:10 - 14:36
Vehicle Number	22325	Total Engine Hours	00:25:16
Total Kms	13	Hours Of Idling	00:02:07 (8%)
Ending Odometer	802769	Hours Over 1800 RPM	00:00:04
Brakes Time	00:03:44	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	29/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
29/07/2020	14:10:47	14:36:03	Key Off	00:25:16	13	00:23:09	00:02:07	6	00:00:00	
				00:25:16	13	00:23:09	00:02:07	6	00:00:00	00:00:00

# Activity Graph

Driver Number	408094944	Report Page	1 of 1
Driver Name	408094944	Date Range	29/07/2020 14:10 - 14:36
Vehicle Number	22325	Total Engine Hours	00:25:16
Total Kms	13	Hours Of Idling	00:02:07 (8%)
Ending Odometer	802769	Hours Over 1800 RPM	00:00:04
Brakes Time	00:03:44	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	29/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



# Administration Report

Driver Number	408094944	Report Page	1 of 1
Driver Name	408094944	Date Range	29/07/2020 14:10 - 14:36
Vehicle Number	22325	Total Engine Hours	00:25:16
Total Kms	13	Hours Of Idling	00:02:07 (8%)
Ending Odometer	802769	Hours Over 1800 RPM	00:00:04
Brakes Time	00:03:44	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	29/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
29/07/2020 14:10:47	Key On at Narellan with an odometer of 802756 and fuel count 310481.0
29/07/2020 14:20:59	Location Narellan -> Campbelltown
29/07/2020 14:32:59	Location Campbelltown -> Customer_Minto
29/07/2020 14:36:02	Idle Event at Customer_Minto for 127 seconds.
29/07/2020 14:36:03	Key Off at Customer_Minto with an odometer of 802769 and fuel count 310487.4
29/07/2020 14:36:08	Completed Trip with Odometer 802769 and Fuel 310487.4