

Operations Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	02/01/2020 06:16 - 07:49
Vehicle Number	23392	Total Engine Hours	01:33:05
Total Kms	25	Hours Of Idling	01:01:43 (66%)
Ending Odometer	525793	Hours Over 1800 RPM	00:00:05
Brakes Time	00:08:41	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	37/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	01:08:38	00:00:09	00:00:10	00:00:11	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	01:09:08
800-900	00:01:02	00:00:01	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:04
900-1000	00:02:55	00:00:01	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:02:57
1000-1100	00:02:53	00:01:09	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:04:03
1100-1300	00:03:29	00:02:06	00:01:13	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:06:49
1300-1400	00:00:35	00:00:07	00:01:33	00:00:12	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:02:27
1400-1500	00:00:20	00:00:00	00:00:00	00:01:04	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:01:24
1500-1600	00:00:13	00:00:00	00:00:00	00:00:18	00:00:39	00:00:00	00:00:00	00:00:00	00:00:00	00:01:10
1600-1700	00:00:12	00:00:00	00:00:00	00:00:00	00:03:21	00:00:00	00:00:00	00:00:00	00:00:00	00:03:33
1700-1800	00:00:08	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:08
1800-2000	00:00:05	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:05
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	01:20:30	00:03:33	00:02:59	00:01:46	00:04:00	00:00:00	00:00:00	00:00:00	00:00:00	01:32:48

Time Analysis



General Operation

Total Fuel	14 litres	Fuel per 100kms	56 litres	Kms Per Litre	1.786
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


Activity Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	02/01/2020 06:16 - 07:49
Vehicle Number	23392	Total Engine Hours	01:33:05
Total Kms	25	Hours Of Idling	01:01:43 (66%)
Ending Odometer	525793	Hours Over 1800 RPM	00:00:05
Brakes Time	00:08:41	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	37/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
02/01/2020	06:16:25	07:49:30	Key Off	01:33:05	25	00:31:22	01:01:43	14	00:00:00	
Report Totals				01:33:05	25	00:31:22	01:01:43	14	00:00:00	00:00:00

Activity Graph

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	02/01/2020 06:16 - 07:49
Vehicle Number	23392	Total Engine Hours	01:33:05
Total Kms	25	Hours Of Idling	01:01:43 (66%)
Ending Odometer	525793	Hours Over 1800 RPM	00:00:05
Brakes Time	00:08:41	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	37/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



Administration Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	02/01/2020 06:16 - 07:49
Vehicle Number	23392	Total Engine Hours	01:33:05
Total Kms	25	Hours Of Idling	01:01:43 (66%)
Ending Odometer	525793	Hours Over 1800 RPM	00:00:05
Brakes Time	00:08:41	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	37/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
02/01/2020 06:16:25	Key On at Depot_Perth with an odometer of 525768 and fuel count 216582.3
02/01/2020 06:54:03	Idle Event at Depot_Perth for 2258 seconds.
02/01/2020 06:55:23	Location Depot_Perth -> Perth
02/01/2020 07:36:22	Idle Event at Perth for 1445 seconds.
02/01/2020 07:49:30	Key Off at Perth with an odometer of 525793 and fuel count 216596.4
02/01/2020 07:49:35	Completed Trip with Odometer 525793 and Fuel 216596.4