

Operations Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	30/01/2020 13:05 - 15:40
Vehicle Number	23392	Total Engine Hours	02:34:19
Total Kms	39	Hours Of Idling	01:50:23 (72%)
Ending Odometer	535463	Hours Over 1800 RPM	00:00:01
Brakes Time	00:09:56	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	52/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	00:37:54	00:02:30	00:00:09	00:00:22	00:00:08	00:00:00	00:00:00	00:00:00	00:00:00	00:41:03
800-900	00:50:29	00:00:07	00:00:00	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:50:37
900-1000	00:32:53	00:00:06	00:00:00	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:33:00
1000-1100	00:03:38	00:01:53	00:00:00	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:05:32
1100-1300	00:04:33	00:02:27	00:00:39	00:00:02	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:07:41
1300-1400	00:01:19	00:00:36	00:00:54	00:00:06	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:02:55
1400-1500	00:00:31	00:00:00	00:00:00	00:01:29	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:02:00
1500-1600	00:00:08	00:00:00	00:00:00	00:01:53	00:02:56	00:00:00	00:00:00	00:00:00	00:00:00	00:04:57
1600-1700	00:00:08	00:00:00	00:00:00	00:00:00	00:06:02	00:00:00	00:00:00	00:00:00	00:00:00	00:06:10
1700-1800	00:00:02	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:02
1800-2000	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:01
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	02:11:36	00:07:39	00:01:42	00:03:55	00:09:06	00:00:00	00:00:00	00:00:00	00:00:00	02:33:58

Time Analysis



General Operation

Total Fuel	25 litres	Fuel per 100kms	64 litres	Kms Per Litre	1.560
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


Activity Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	30/01/2020 13:05 - 15:40
Vehicle Number	23392	Total Engine Hours	02:34:19
Total Kms	39	Hours Of Idling	01:50:23 (72%)
Ending Odometer	535463	Hours Over 1800 RPM	00:00:01
Brakes Time	00:09:56	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	52/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
30/01/2020	13:05:43	15:40:02	Key Off	02:34:19	39	00:43:56	01:50:23	25	00:00:00	
Report Totals				02:34:19	39	00:43:56	01:50:23	25	00:00:00	00:00:00

Activity Graph

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	30/01/2020 13:05 - 15:40
Vehicle Number	23392	Total Engine Hours	02:34:19
Total Kms	39	Hours Of Idling	01:50:23 (72%)
Ending Odometer	535463	Hours Over 1800 RPM	00:00:01
Brakes Time	00:09:56	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	52/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



Administration Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	30/01/2020 13:05 - 15:40
Vehicle Number	23392	Total Engine Hours	02:34:19
Total Kms	39	Hours Of Idling	01:50:23 (72%)
Ending Odometer	535463	Hours Over 1800 RPM	00:00:01
Brakes Time	00:09:56	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	52/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
30/01/2020 13:05:43	Key On at Perth with an odometer of 535424 and fuel count 220857.6
30/01/2020 13:42:03	Idle Event at Perth for 2180 seconds.
30/01/2020 14:23:53	Location Perth -> Depot_Perth
30/01/2020 15:39:14	Idle Event at Depot_Perth for 4443 seconds.
30/01/2020 15:40:02	Key Off at Depot_Perth with an odometer of 535463 and fuel count 220882.6
30/01/2020 15:40:07	Completed Trip with Odometer 535463 and Fuel 220882.6