

# Operations Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	01/06/2020 08:18 - 12:07
Vehicle Number	23392	Total Engine Hours	03:49:01
Total Kms	319	Hours Of Idling	00:11:26 (5%)
Ending Odometer	572615	Hours Over 1800 RPM	00:00:41
Brakes Time	00:02:28	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	22/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

## Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	00:13:40	00:00:20	00:00:12	00:01:51	00:03:42	00:00:00	00:00:00	00:00:00	00:00:00	00:19:45
800-900	00:00:20	00:00:01	00:00:01	00:00:06	00:00:10	00:00:00	00:00:00	00:00:00	00:00:00	00:00:38
900-1000	00:00:35	00:00:01	00:00:00	00:00:05	00:00:10	00:00:00	00:00:00	00:00:00	00:00:00	00:00:51
1000-1100	00:01:10	00:00:21	00:00:00	00:00:05	00:00:11	00:00:00	00:00:00	00:00:00	00:00:00	00:01:47
1100-1300	00:02:15	00:01:00	00:00:45	00:00:11	00:00:20	00:00:00	00:00:00	00:00:00	00:00:00	00:04:31
1300-1400	00:00:34	00:00:14	00:01:30	00:00:49	00:00:09	00:00:00	00:00:00	00:00:00	00:00:00	00:03:16
1400-1500	00:00:07	00:00:02	00:00:00	00:15:54	00:00:09	00:00:00	00:00:00	00:00:00	00:00:00	00:16:12
1500-1600	00:00:02	00:00:00	00:00:00	00:26:03	00:37:52	00:00:00	00:00:00	00:00:00	00:00:00	01:03:57
1600-1700	00:00:04	00:00:00	00:00:00	00:00:01	01:56:42	00:00:00	00:00:00	00:00:00	00:00:00	01:56:47
1700-1800	00:00:00	00:00:00	00:00:00	00:00:00	00:00:10	00:00:00	00:00:00	00:00:00	00:00:00	00:00:10
1800-2000	00:00:00	00:00:00	00:00:00	00:00:08	00:00:07	00:00:00	00:00:00	00:00:00	00:00:00	00:00:15
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:24	00:00:00	00:00:00	00:00:00	00:00:00	00:00:24
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	00:18:47	00:01:59	00:02:28	00:45:13	02:40:06	00:00:00	00:00:00	00:00:00	00:00:00	03:48:33

## Time Analysis



## General Operation

Total Fuel	157 litres	Fuel per 100kms	49 litres	Kms Per Litre	2.032
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


# Activity Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	01/06/2020 08:18 - 12:07
Vehicle Number	23392	Total Engine Hours	03:49:01
Total Kms	319	Hours Of Idling	00:11:26 (5%)
Ending Odometer	572615	Hours Over 1800 RPM	00:00:41
Brakes Time	00:02:28	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	22/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
01/06/2020	08:18:14	12:07:15	Key Off	03:49:01	319	03:37:35	00:11:26	157	00:00:00	
Report Totals				03:49:01	319	03:37:35	00:11:26	157	00:00:00	00:00:00

# Activity Graph

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	01/06/2020 08:18 - 12:07
Vehicle Number	23392	Total Engine Hours	03:49:01
Total Kms	319	Hours Of Idling	00:11:26 (5%)
Ending Odometer	572615	Hours Over 1800 RPM	00:00:41
Brakes Time	00:02:28	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	22/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



# Administration Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	01/06/2020 08:18 - 12:07
Vehicle Number	23392	Total Engine Hours	03:49:01
Total Kms	319	Hours Of Idling	00:11:26 (5%)
Ending Odometer	572615	Hours Over 1800 RPM	00:00:41
Brakes Time	00:02:28	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	22/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
01/06/2020 08:18:14	Key On at WA with an odometer of 572296 and fuel count 237480.4
01/06/2020 08:21:15	Idle Event at WA for 181 seconds.
01/06/2020 11:01:48	Idle Event at WA for 130 seconds.
01/06/2020 11:30:40	Idle Event at WA for 375 seconds.
01/06/2020 12:07:15	Key Off at WA with an odometer of 572615 and fuel count 237637.2
01/06/2020 12:07:20	Completed Trip with Odometer 572615 and Fuel 237637.2