

Operations Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	29/07/2020 16:58 - 18:37
Vehicle Number	23392	Total Engine Hours	01:39:03
Total Kms	38	Hours Of Idling	00:52:13 (53%)
Ending Odometer	594419	Hours Over 1800 RPM	00:00:01
Brakes Time	00:07:37	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	51/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Speed Vs RPM Matrix

	0-60	60-70	70-80	80-90	90-100	100-103	103-106	106+	Aux	Total
0-800	00:40:00	00:00:02	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:40:02
800-900	00:12:33	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:12:33
900-1000	00:13:58	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:13:58
1000-1100	00:04:00	00:02:06	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:06:06
1100-1300	00:04:43	00:02:18	00:00:56	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:07:57
1300-1400	00:00:56	00:00:06	00:03:24	00:00:35	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:05:01
1400-1500	00:00:29	00:00:00	00:00:00	00:07:04	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:07:33
1500-1600	00:00:15	00:00:00	00:00:00	00:01:50	00:00:26	00:00:00	00:00:00	00:00:00	00:00:00	00:02:31
1600-1700	00:00:11	00:00:00	00:00:00	00:00:00	00:02:52	00:00:00	00:00:00	00:00:00	00:00:00	00:03:03
1700-1800	00:00:05	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:05
1800-2000	00:00:01	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:01
2000-2100	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
2100+	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00
Total	01:17:11	00:04:32	00:04:20	00:09:29	00:03:18	00:00:00	00:00:00	00:00:00	00:00:00	01:38:50

Time Analysis



General Operation

Total Fuel	20 litres	Fuel per 100kms	53 litres	Kms Per Litre	1.900
PTO Time	00:00:00	PTO Fuel	0 litres	PTO Dist	0 kms


Activity Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	29/07/2020 16:58 - 18:37
Vehicle Number	23392	Total Engine Hours	01:39:03
Total Kms	38	Hours Of Idling	00:52:13 (53%)
Ending Odometer	594419	Hours Over 1800 RPM	00:00:01
Brakes Time	00:07:37	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	51/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Date	Start Time	Stop Time	Trip Ending	Travel Time	Distance Kms	Rolling Time	Idle Time	Fuel Litres	Excess Speed	Stop Time
29/07/2020	16:58:02	18:37:05	Key Off	01:39:03	38	00:46:50	00:52:13	20	00:00:00	
Report Totals				01:39:03	38	00:46:50	00:52:13	20	00:00:00	00:00:00

Activity Graph

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	29/07/2020 16:58 - 18:37
Vehicle Number	23392	Total Engine Hours	01:39:03
Total Kms	38	Hours Of Idling	00:52:13 (53%)
Ending Odometer	594419	Hours Over 1800 RPM	00:00:01
Brakes Time	00:07:37	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	51/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	



Administration Report

Driver Number	401480394	Report Page	1 of 1
Driver Name	Demi Munro	Date Range	29/07/2020 16:58 - 18:37
Vehicle Number	23392	Total Engine Hours	01:39:03
Total Kms	38	Hours Of Idling	00:52:13 (53%)
Ending Odometer	594419	Hours Over 1800 RPM	00:00:01
Brakes Time	00:07:37	Hours Over 106 Km/Hr	00:00:00
Brakes Count/Km	51/	Hours Over 103 Km/Hr	00:00:00
Break Time	00:00:00	Hours Over 100 Km/Hr	00:00:00
Route		Trailer	

Time	Item
29/07/2020 16:58:02	Key On at Perth with an odometer of 594381 and fuel count 247330.3
29/07/2020 17:28:21	Idle Event at Perth for 1819 seconds.
29/07/2020 18:13:01	Location Perth -> Depot_Perth
29/07/2020 18:36:19	Idle Event at Depot_Perth for 1314 seconds.
29/07/2020 18:37:05	Key Off at Depot_Perth with an odometer of 594419 and fuel count 247350.9
29/07/2020 18:37:10	Completed Trip with Odometer 594419 and Fuel 247350.9